

FIRE RELATED PRODUCT RECALL NOTIFICATION

MerCruiser 5.0L, 350 Mag & 6.2L Marine Engines	
29 April 2012 ACTION - New Zealand recall	
Problem	<p>The main engine wire harness may be routed incorrectly allowing it to be too close to the DTS shift actuator.</p> <p>Repeated movement of the DTS shift actuator arm may cause the engine wire harness shielding to wear through, exposing the wires and causing a direct short circuit to ground, which could create an ignition source prior to the fuses interrupting the circuit.</p>
Details	<p>This recall effects: Serial No. Range: 2A014073 – 2A050912 / 2012 Models</p>
What to do	<p>People with an affected engine (as per the above serial range) should contact their nearest Mercury MerCruiser Dealer who will arrange for the engine to be inspected and rectified if required at the expense of Marine Power International Pty Ltd.</p> <p>The boat should not be operated until the repair has been completed.</p>
More Information	<p>Recall notice</p> <p>For your nearest dealer location please refer to the Dealer Locator on the following website www.mercurymarine.co.nz</p> <p>You can also contact or Mercury Marine at merc_info@mercmarine.com</p>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.