

Fire Related Product Recall Notice



Date issued: 17 October 2016

Bosch freestanding gas cookers

Bosch New Zealand have issued a voluntary safety recall on the gas connection fitted to certain models of freestanding gas cookers.



Problem

There is potential damage to a gas connection fitting. In certain circumstances, gas can escape and in rare cases a risk of explosion can arise.



Details

A limited number of freestanding gas cookers which were manufactured between January 2009 and October 2011 are affected. To determine if your cooker is affected, note down the model number (E-Nr.) and the batch number (FD) which can be found on the appliance as shown below.



E-Nr: HSV745020N / 04 FD: 8912 Z-Nr: 100001

What to do

Contact the Bosch website www.bosch-home.co.nz and enter the details of the cooker to determine if it is an affected model. Owners of an affected appliance should turn off the gas supply to the appliance immediately and not use it until the connection fitting has been replaced. Bosch are offering every owner of an affected appliance the free replacement of the connection fitting by an authorized service technician. The replacement is carried out at the owner's home, resolves the issue completely, is free of charge and does not require any additional expense or effort on the part of the owner.

Contact

For further information contact Bosch by visiting www.bosch-home.co.nz or on 0800 245 700 or 0800 807 723

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.