

FIRE RELATED PRODUCT RECALL NOTIFICATION

Goldair Oil Column Heaters

15 April 2010 (First recalled 20 July 2009)

ACTION - New Zealand recall

Problem	A possible manufacturing fault has been identified. A faulty tip-over switch could cause a hole to form in the oil column. Subsequently, oil could leak out and possibly catch alight.
Details	<p>The following models are affected:</p> <ul style="list-style-type: none">• Goldair 7 fin oil column heater, model FOL507• Goldair 9 fin oil column heater, model FOL509• Goldair 11 fin oil column heater, model FOL511 <p>Sold exclusively through Farmers stores between February 2009 and July 2009.</p>
What to do	Cease using the heater immediately and contact 0800 232 633 for instructions on how to receive a replacement heater. For further information, email: heaters@goldair.co.nz
More Information	No recall notice was issued, refer to the links below: Consumer website Farmers article

This notification has been compiled using information from other sources, every attempt has been made to ensure its accuracy by the Fire Research and Investigation Unit.