



FIRE RELATED PRODUCT RECALL NOTIFICATION

Holden Fuel Leak Problem	
16 January 2008	ACTION - New Zealand recall
Problem	A fuel line in the engine bay could rub against a clip, potentially causing wear and a fuel leak.
Details	Affected models are all WM Statesmans, V6 VE Commodores, V6 Ute and Caprice long-wheelbase models built since mid-2006.
What to do	Owners of affected models will be contacted by Holden. For any further queries contact your local Holden dealer service department.
More Information	No recall notice was issued, refer to the links below: Stuff news article Consumer website

This notification has been compiled using information from other sources, every attempt has been made to ensure its accuracy by the Fire Research and Investigation Unit.