

# Fire Related Product Recall Notice



Date issued: 7 June 2017


## Beko Dryer

Beko has been made aware of a small number of incidents involving our 6kg & 7kg Condenser Tumble Dryers manufactured between May 2012 and October 2012, where an electrical component has failed and overheated, leading to a potential risk of fire.

### Problem

The capacitor may fail and overheat, potentially leading to risk of fire.

No incidents have been reported in Australia or New Zealand.



### Details

#### Product Identifiers

Model number: DCU8330GX

Affected serial numbers:

12-xxxxxxx-06

12-xxxxxxx-07

### What to do

Beko are contacting customers directly to check and repair machines.

### Contact

<https://dryersafety.beko.co.uk/>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.