



## FIRE RELATED PRODUCT RECALL NOTIFICATION

<b>Apple iPod nano</b>	
<b>28 Nov 2011</b>	<b>ACTION - New Zealand recall</b>
Problem	The battery in the iPod nano (1st generation) may overheat and pose a safety risk.
Details	This recall effects iPod nano (1st generation), sold nationwide from September 2005 to December 2006.
What to do	Stop using your iPod nano (1st generation) and visit the following website to arrange a replacement unit, free of charge.  <a href="http://www.apple.com/nz/support/ipodnano_replacement/">www.apple.com/nz/support/ipodnano_replacement/</a>  Your iPod nano serial number will be required to verify that it is eligible for this program.
More Information	<a href="#">Consumer website</a> <a href="#">Apple NZ website</a>

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.