

FIRE RELATED PRODUCT RECALL NOTIFICATION

Bosch Dishwashers	
13 December 2012	ACTION - New Zealand recall
Problem	In some circumstances, the components in the dishwasher's control module may fail creating a fire hazard.
Details	<p>BSH Home Appliances Ltd is issuing a recall on specified Bosch dishwashers sold in new Zealand through various retailers.</p> <p>Models manufactured between 2000 and 2006 with the following model numbers are affected: SGI4335AU; SGI4345AU; SGI4347AU; SGI43A25AU; SGI43A45AU; SGI43A55AU; SGI4705AU; SGI4715AU; SGI53A55AU; SGS4332AU; SGS4352AU; SGS43A92AU; SGS43B22AU; SGS43B42AU; SGS4702AU; SGS4712AU; SGS5332AU; SGS53A52AU; SRI43A05AU; SRS5302AU.</p> <p>The model identification numbers can be found on the top inside edge of the door panel.</p>
What to do	Cease using the dishwasher immediately and switch it off at the Socket outlet. Check the model number and contact the Bosch Repair team between 9am and 5pm, Monday to Friday, on 0800 886 551 or visit www.bosch-home.co.nz/repair to arrange a free, in home repair.
More Information	Recall notice. www.bosch-home.co.nz/repair



This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.