New Zealand Fire Service Fire Research & Investigation Unit



FIRE RELATED PRODUCT RECALL NOTIFICATION

Mazda 6	
27 March 2013	ACTION - New Zealand recall
Problem	Mazda are recalling the all new Mazda 6 which has been on sale for just a few months worldwide as a precautionary measure after an incident in Australia.
Details	The DC/DC converter which reduces current from the generator from 25V down to 12V may have a fault which could result in a fire.
	The converter is located under the front passengers seat.
	While a fire resulting from the fault is considered as unlikely, it is a possibility.
	Mazda will be contacting all owners of these vehicles.
What to do	Check with your Mazda dealer or using your Vin number through the website below to see if your vehicle is part of this recall to arrange a repair free of charge.
More Information	Call 0800 800 626 for more information or contact your local Mazda Dealer. Mazda Safety Recalls website



This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.