New Zealand Fire Service Fire Research & Investigation Unit



FIRE RELATED PRODUCT RECALL NOTIFICATION

Can-Am Commander Off Road Utility Vehicle		
22 December 2012		ACTION - New Zealand recall
Problem	_	Am Commander side-by-side use of a potential fire hazard.
Details	A potential fire hazard can debris laden water (310mm) Debris build-up can ignite we exhaust.	. ,
What to do	J .	your vehicle has been fitted a . Contact your authorised Can-
More Information	Recall Letter	

This notification has been compiled using information from external sources for the promotion of fire safety. Although care has been taken in preparing the information published, the New Zealand Fire Service does not guarantee the accuracy of it. The Fire Service is not responsible for any errors or omissions and accepts no liability whatsoever for any loss or damage howsoever arising.